



Date: 31.01.2018

## Annexure - I

## 1.0 Dry Heat / High Temperature Test as per IS: 9000 Part 3 section 5:

#### 1.1 Test Conditions:

ICAT Sample I.D	ICAT/AEEL/56955/01
DUT Operation During Test	Powered ON Mode
Voltage Supplied After Test	12V

### 1.2 Test Specifications:

The test shall be carried out in accordance with Indian Standard IS: 9000 (Part 3/Sec 5) the device shall be subjected to temperature of  $70 \pm 2$ °C for 16 h in high temperature. Test with device in working condition. The recovery period shall be 2 h.

### 1.3 Acceptance Criteria:

Device during and after the high temperature test the VLT with Emergency Button shall be tested for the connectivity to server and its capability to send two location messages.

## 1.4 Observations and Result:

## Observation:

After test DUT was visually, functionally and mechanically inspected, no abnormality observed.

### Result:

### **Before Test:**

#### **Emergency String:**

\$Header,iTriangle,EMR,861693034634147,NM,19122017104943,A,28.359272,N,76.927963,E,242.0,0.0,5,G,KA0 112000,+9164061023\*44

## **PVT Data String:**

 $$Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, L, 861693034634147, KA0112000, 1, 19122017, 104923, 28.359289, N, 76.927963, E, 0.0, 171, 12, 242.0, L.29, L.01, AirTel, 1, 1, 11.9, 4, 0, 1, C, 25, 404, 10, 0209, 6d17, 28, aa1a, 0209, 26, 4333, 0209, 18, d2fb, 0209, 17, b2f8, 0209, 0001, 00, 087752, 0.0, 0.0, 0, () * 76$ 

#### **During Test:**

#### **Emergency String:**

\$Header,iTriangle,EMR,861693034634147,NM,20122017041925,V,0.0000000,N,0.0000000,E,0.0,0.0,0,G,KA01I20 00,+9164061023\*5B

## **PVT Data String:**

 $$Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, L, 861693034634147, KA0112000, 0, 20122017, 041904, 0.000000, N, 0.000000, E, 0.0, 0, 0, 0.0, 0.000, 0.0, AirTel, 1, 1, 11.9, 4.1, 1, C, 15, 404, 10, 0209, 6d17, 19, 4333, 0209, 10, b2fa, 0209, 07, 6d16, 0209, 19, ffff, 0000, 0001, 00, 088343, 0.0, 0.0, 0, ()*4E$ 

Prepared By		Checked By	
	SEE FOR AUTOMOTES		
90	MANESS R. M. MANESS R. M.		
Soul Sonia Nain		MADHUSUDAN JOSHI	Page 5 of 65
Assistant Manager	_	Deputy Gueral Manager	Drwg (03Nos.) [56955]





Date: 31.01.2018

# Annexure - I (Continued)

## After Test:

### **Emergency String:**


\$Header,iTriangle,EMR,861693034634147,NM,20122017044044,A,28.359318,N,76.927780,E,228.0,0.0,0,G,KA01 12000,+9164061023\*42

### **PVT Data String:**

\$Header,iTriangle,1\_36T02B0164MAIS\_6,EA,10,L,861693034634147,KA01I2000,1,20122017,044035,28.359318, N,76.927780,E,0.0,61,9,228.0,1.31,0.95,AirTel,1,1,11.9,4.0,1,C,23,404,10,0209,6d17,27,4333,0209,25,9cf1,0209, 24,b2fa,0209,24,6d18,0209,0001,00,088428,0.0,0.0,0,()\*77

Satisfactory.









Date: 31.01.2018

## Annexure - II

## 2.0 Cold Test as per IS: 9000 Part 2 section 4 - 1977:

### 2.1 Test Conditions:

ICAT Sample I.D	ICAT/AEEL/56955/01
DUT Operation During Test	Powered ON Mode
Voltage Supplied After Test	12V

### 2.2 Test Specifications:

The test shall be carried out in accordance with IS 9000 (Part 2/Sec 4 - 1977). The device under test shall be subjected to temperature of  $-10 \pm 2$ °C for 2 h with device in working condition. The recovery period shall be 2 h.

## 2.3 Acceptance Criteria:

Device during and after the cold test, the VLT with Emergency Button shall be tested for the connectivity to server and its capability to send two location messages.

## 2.4 Observations and Result:

### Observation:

After test DUT was visually, functionally and mechanically inspected no abnormality observed.

### Result:

## **Before Test:**

#### **Emergency Data:**

\$Header,iTriangle,EMR,861693034634147,NM,20122017044044,A,28.359318,N,76.927780,E,228.0,0.0,0,G,KA01I2000,+9164061023\*42

## **PVT Data:**

 $$Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, L, 861693034634147, KA01I2000, 1, 20122017, 044035, 28.359318, N, 76.927780, E, 0.0, 61, 9, 228.0, 1.31, 0.95, Air Tel, 1, 1, 11.9, 4.0, 1, C, 23, 404, 10, 0209, 6d17, 27, 4333, 0209, 25, 9cf1, 0209, 24, b2fa, 0209, 24, 6d18, 0209, 0001, 00, 088428, 0.0, 0.0, 0, ()*77$ 

## **During Test:**

#### **Emergency Data:**

\$Header,iTriangle,EMR,861693034634147,NM,20122017061034,V,0.000000,N,0.0000000,E,0.0,0.0,G,KA0 112000,+9164061023\*50

## **PVT Data:**

 $$Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, L, 861693034634147, KA01I2000, 0, 20122017, 061014, 0.000000, N, 0.000000, E, 0.0, 0, 0.00, 0.00, 0.00, AirTel, 1, 1, 11.8, 4.0, 1, C, 12, 404, 10, 0209, 6d17, 20, b2f8, 0209, 11, d2fc, 0209, 19, fffff, 0000, 18, fffff, 0000, 0001, 00, 088903, 0.0, 0.0, 0, ()*1B$ 

Prepared By		Checked By	
SONIA NAIN Assistant Manager	ENGLISH SCHOOL SCHOOL STATES	MADHUSUDAN JOSHI Deputy General Manager	Page 7 of 65 + Drwg (03Nos.) [56955]





Date: 31.01.2018

## **After Test:**

## **Emergency Data:**

\$Header,iTriangle,EMR,861693034634147,NM,20122017075616,A,28.358576,N,76.927795,E,225.0,0.0,1,G,KA01I2000,+9164061023\*46

## **PVT Data:**

\$Header,iTriangle,1\_36T02B0164MAIS\_6,EA,10,L,861693034634147,KA01I2000,1,20122017,075532,28.35 8578,N,76.927788,E,0.0,188,10,226.0,1.88,1.65,AirTel,1,1,11.8,4.0,1,C,18,404,10,0209,6d17,30,d2fc,0209, 28,6d18,0209,23,b2f8,0209,23,4333,0209,0001,00,089367,0.0,0.0,0,()\*28

Satisfactory.



Prepared By

Checked By

Page
8 of 65
+
Sonia Nain
Assistant Manager

Page
(3 Nos.)
[56955]





C T O G N O O 3 5

Date: 31.01.2018

## Annexure - III

3.0 Temperature Shock Test as per AIS 140 Cl. No. 6.3.3 (Sr. No. 4):

#### 3.1 Test Conditions:

ICAT Sample I.D	ICAT/AEEL/56955/05
DUT Operation During Test	Non-Operating Mode
Voltage Supplied After Test	12V

### 3.2 Test Specifications:

High Temperature: +70±2 °C Low Temperature: -10±2 °C

Exposure time would be 3 hours/cycle (i.e. 1.5 hrs each temperature)

Number of cycles:2

## 3.3 Acceptance Criteria:

After the test the VLT with Emergency Button shall be tested for the connectivity to server and its capability to send two location messages.

## 3.4 Observations and Result:

#### Observation:

After test DUT was visually, functionally and mechanically inspected no abnormality observed.

## Result:

#### **Before Test:**

### **Emergency Data:**

\$Header,iTriangle,EMR,861693034634386,NM,27122017084844,A,28.358870,N,76.927979,E,255.0,0.0, 0,G,KA01KA1134,+917406466262\*0D

### **PVT Data:**

\$Header,iTriangle,1\_36T02B0164MAIS\_6,EA,10,±,861693034634386,KA01KA1134,1,27122017,084833, 28.358870,N,76.927979,E,0.0,180,17,255.0,1,20,0.61,AirTel,1,1,11.7,4.0,1,C,23,404,10,0209,6d18,32,6 d17,0209,25,b2f8,0209,21,4333,0209,20,6e9d,0209,0001,00,000126,0.0,0.0,0,()\*57

### **After Test:**

#### **Emergency Data:**

\$Header,iTriangle,EMR,861693034634386,NM,28122017042216,A,28.359207,N,76.928032,E,248.0,0.0, 0,G,KA01KA1134,+917406466262\*0B

## **PVT Data:**

 $$\ \ $$ Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, L, 861693034634386, KA01KA1134, 1, 28122017, 042212, 28.359205, N, 76.928032, E, 0.0, 354, 13, 248.0, 1.79, 0.85, AirTel, 1, 1, 11.5, 4.0, 1, C, 24, 404, 10, 0209, 6d17, 25, d2fc, 0209, 25, d2fb, 0209, 23, b2f8, 0209, 17, b2fa, 0209, 0001, 00, 000420, 0.0, 0, 0, ()*66$ 

Satisfactory.

Prepared By

Checked By

Page
9 of 65
+
SONIA NAIN
Assistant Manager

Deputy General Manager

Checked By

Page
9 of 65
+
Drwg (03Nos.)
[56955]







Date: 31.01.2018

# Annexure - IV

## 4.0 Damp Heat Cycle Test as per IS 9000 Part 5 Section 2 - 1981:

#### 4.1 Test Conditions:

ICAT Sample I.D	ICAT/AEEL/56955/04
DUT Operation During Test	Powered ON Mode
Voltage Supplied After Test	12V

## 4.2 Test Method & Specifications

The device under test shall be tested according to IS 9000 (Part 5/Sec 2 - 1981). The test is carried out at +25° to +55° C, Humidity 95%. Six cycles (each test cycle of 24 h) shall be run with device in off condition. Functional test shall be carried out with power in 'On condition' at start of 2nd, 4th and 6th cycle.

## 4.3 Acceptance Criteria:

Device during and after the test the VLT with Emergency Button shall be tested for the connectivity to server and its capability to send two location messages.

#### 4.4 Observation and Results:

#### Observation:

After test DUT was visually, functionally and mechanically inspected no abnormality observed.

## Result:

## **Before Test:**

## **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634170,NM,19122017065624,A,28.359198,N,76.927849,E,219.0,0.0, 2,G,KA01I2000,+917406466262\*4C

### **PVT IP Data:**

\$Header,iTriangle,1\_37T02B0164MAIS,EA,10,L,861693034634170,KA01I2000,1,19122017,065620,28.3 59215,N,76.927841,E,0.0,106,10,219.0,1.22,0.95,AirTel,1,1,11.8,4.0,1,C,25,404,10,0209,4333,41,6d17, 0209,29,6d18,0209,25,d2fc,0209,25,aa1a,0209,0001,00,000529,0.0,0.0,0,()\*44

### **During Test:**

#### **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634170,NM,20122017085209,A,28.358698,N,76.928085,E,247.0,0.0, 0,G,KA01I2000,+917406466262\*4B

## **PVT IP Data:**

\$Header,iTriangle,1\_37T02B0164MAIS,EA,10,L,861693034634170,KA01i2000,1,20122017,085207,28.3 58685,N,76.928085,E,0.0,356,10,247.0,1.81,1.07,AirTel,0,1,11.6,4.0,1,C,30,404,10,0209,6d17,31,4333,0209.26.6d18.0209.26.b2f8.0209.24.6e9d.0209.0000.00.002730.0.0.0 0 ()\*46

Prepared By		Checked By	
	FOR AUTOMORPHICAL PROPERTY OF THE PROPERTY OF		a
Soria	MANES & A TE		Page 10 of 65





C T O G N O O 3 5

Date: 31.01.2018

## After Test:

## **Emergency IP Data:**

#### **PVT IP Data:**

 $$Header, iTriangle, 1\_37T02B0164MAIS, EA, 10, L, 861693034634170, KA01I2000, 1, 26122017, 044920, 28.359045, N, 76.928009, E, 0.0, 182, 13, 240.0, 1.10, 0.76, AirTel, 1, 1, 11.6, 4.0, 1, C, 23, 404, 10, 0209, 6d17, 23, d2fc, 0209, 23, aa1a, 0209, 15, b2f8, 0209, 13, d2fb, 0209, 0001, 00, 002830, 0.0, 0.0, 0, ()*5A$ 

Satisfactory



Prepared By

Checked By

Page
11 of 65

SONIA NAIN
Assistant Manager

Deputy General Manager

Checked By

Page
11 of 65

Deputy General Manager

S6955





Date: 31.01.2018

# Annexure – V

## 5.0 Salt Spray Test as per Clause 4.8 of IS 10250:

#### 5.1 Test Conditions:

ICAT Sample I.D	ICAT/AEEL/56955/05
DUT Operation During Test	Non-Operating Mode

## 5.2 Test Method, Specifications:

Solution: 5%NACL Temperature: 35±3°C Test Duration: 96 Hrs

## 5.3 Acceptance Criteria:

The VLT with Emergency Button shall be tested for the connectivity to server and its capability to send two location messages.

## 5.4 Observation and Result:

## Observation:

After test DUT was visually, functionally and mechanically inspected no abnormality observed. No corrosion observed.

#### Result:

## **Before Test:**

## **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634386,NM,19122017092142,A,28.359241,N,76.927910,E,234.0,0.0, 3,G,KA01KA1134,+917406466262\*74

## **PVT IP Data:**

\$Header,iTriangle,1\_36T02B0164MAIS\_6,EA,10,L,861693034634386,KA01KA1134,1,19122017,092112, 28.359200,N,76.927971,E,0.0,98,9,233.0,1.25,0.91,AirTel,1,1,11.9,4.0,1,C,22,404,10,0209,6d17,21,433 3,0209,18,aa1a,0209,17;b2fa,0209,14,6d18,0209,0001,00,009871,0.0,0.0,7,()\*67

## **After Test:**

#### **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634386,NM,26122017043028,A,28.358980,N,76.928001,E,237.0,0.0, 0,G,KA01KA1134,+917406466262\*06

### **PVT IP Data:**

 $$Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, L, 861693034634386, KA01KA1134, 1, 26122017, 043018, 28.358965, N, 76.928001, E, 0.0, 332, 13, 237.0, 1.16, 0.77, AirTel, 0, 1, 11.7, 4.0, 1, C, 18, 404, 10, 0209, 6d17, 29, 6d18, 0209, 27, aa1a, 0209, 27, d2fc, 0209, 21, b2f8, 0209, 0000, 000, 012096, 0.0, 0.0, 0, () *67$ 

Satisfactory.

Prepared By		Checked By	
SONIA NAIN Assistant Manager	THE FOR AUTOMOTIVE TO THE STATE OF THE STATE	MADHUSUDAN JOSHI Deputy General Manager	Page 12 of 65 + Drwg (03Nos.) [56955]





Date: 31.01.2018

## Annexure - VI

## 6.0 High Voltage Test as per ISO 16750 - 2: 2010:

#### 6.1 Test Conditions:

ICAT Sample I.D	ICAT/AEEL/56955/03
DUT Operation During Test	Powered ON Mode
Voltage Supplied Before & After Test	12V

### 6.2 Test Specifications:

The test is conducted to ensure service life requirements & functionality. The device under test shall be operated for 60 minutes at 18 V for 12 V systems & 36 V for 24 V systems.

### 6.3 Acceptance Criteria:

The VLT with Emergency Button shall be tested during and after the test for the connectivity to server and its capability to send two location messages.

### 6.4 Observations and Result:

### Observation:

After test DUT was visually, functionally and mechanically inspected, no abnormality observed.

#### Result:

a.) High Voltage for 12V system at 18V.

### **Before Test:**

## **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034637124,NM,20122017091331,A,28.358845,N,76.928108,E,177.0,0.0,17,G,KA01I 2000,+917406466262\*7A

#### **PVT IP Data:**

## **During Test:**

#### **PVT IP Data:**

## After Test:

## **Emergency IP Data:**

#### **PVT IP Data:**

\$Header,iTriangle,1\_36T02B0164MAIS\_6,EA,10,L,861693034637124,KA01I2000,1,20122017,102414,28.358917,N,76.928123,E,0.0,99,7,248.0,1.52,1.27,AirTel,1,1,17.4,4.0,1,C,20,404,10,0209,6d17,26,4333,0209,20,d2fc,0209,19,6

Prepared By		Checked By	
SUNIA NAIN Assistant Manager	ME FOR AUTOMOTIVE CONTROL OF THE PARTY OF TH	MADHUSUDAN JOSHI Deputy General Manager	Page 13 of 65 + Drwg (03Nos.) [56955]





Date: 31.01.2018

e9d,0209,17,6d16,0209,0001,00,023916,0.0,0.0,1,()\*62

### b.) High Voltage For 24V system at 36V.

#### **Before Test:**

### **Emergency IP Data:**

\$Header, iTriangle, EMR, 861693034637124, NM, 20122017102418, A, 28.358913, N, 76.928101, E, 248.0, 0.0, 4, G, KA0112000, +917406466262\*4B

## **PVT IP Data:**

 $$Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, L, 861693034637124, KA01I2000, 1, 20122017, 102414, 28.358917, N, 76.928123, E, 0.0, 99, 7, 248.0, 1.52, 1.27, AirTel, 1, 1, 1, 17.4, 4.0, 1, C, 20, 404, 10, 0209, 6d17, 26, 4333, 0209, 20, d2fc, 0209, 19, 6e9d, 0209, 17, 6d16, 0209, 0001, 00, 023916, 0.0, 0.0, 1, ()*62$ 

## **During Test:**

### **Emergency IP Data:**

 $\label{thm:condition} $$ Header, iTriangle, EMR, 861693034637124, NM, 20122017104944, A, 28.359324, N, 76.927628, E, 292.0, 0.0, 7, G, KA01|2000, +917406466262*79$ 

### **PVT IP Data:**

 $$Header, iTriangle, 1\_36T02B0164MAIS\_6, EA, 10, I\_861693034637124, KA01I2000, 1, 20122017, 104930, 28.359272, N, 76.927696, E., 0.0, 306, 3, 292.0, 99.99, 99.99, AirTel, 1, 1, 0.0, 4.0, 1, C, 21, 404, 10, 0209, 6d17, 28, 6d18, 0209, 23, aa1a, 0209, 23, d2fb, 0209, 22, 6e9d, 0209, 0001, 00, 024082, 0.0, 0.0, 1, ()*23$ 

#### After Test:

### **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034637124,NM,20122017112958,A,28.359457,N,76.927895,E,277.0,0.0,3,G,KA01I2 000,+917406466262\*4F

#### **PVT IP Data:**

Satisfactory.

Innovation • Service • Excellence


Prepared By

Checked By

Page
14 of 65
+
SONIA NAIN

Assistant Manager

MADHUSULAN JOSHI
Drwg (03Nos.)
[56955]





C T O G N O O 3 5

Date: 31.01.2018

## Annexure - VII

## 7.0 Shock Test as per standard IS: 9000 (Part 7-2006):

#### 7.1 Test Conditions:

ICAT Sample I.D		ICAT/AEEL/56955/04		
DUT Operation Du	ıring Test	Non-Operating Mode	•	

## 7.2 Test Method and Specifications:

Impact test carried out as per IS 9000 Part 7.

Severity level=15g

Impact duration =11 ms

Impact type= Half sine

Number of impact=9 (3 on each axis)

## 7.3 Acceptance Criteria:

After the shock test, the VLT with Emergency Button shall be tested for the connectivity to server and its capability to send two location messages.

## 7.4 Observation and Results:

### **Observations:**

No deformation, crack, looseness or any other harmful defect observed on the DUT(s) after the test. DUT was functionally OK in operation after the test.

#### Results:

## **Before Test:**

## **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634170,NM,26122017105619,A,28.359192,N,76.928047,E,246.0,0.0,0,G,KA01I2000,+917406466262\*42

#### **PVT IP Data:**

\$Header,iTriangle,1\_37T02B0164MAIS,EA,10,L,861693034634170,KA0112000,1,26122017,105612,28.35 9167,N,76.928047,E,0.0,56,12,246.0,1.11,0.84,AirTel,0,1,11.6,4.0,1,C,22,404,10,0209,6d17,27,aa1a,0209 ,26,d2fc,0209,23,6d18,0209,18,d2fb,0209,0000,00,003126,0.0,0.0,0,()\*26

## **After Test:**

## **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634170,NM,26122017115956,A,28.358883,N,76.928055,E,241.0,0.0,0 ,G,KA01I2000,+917406466262\*4B

## **PVT IP Data:**

 $$ Header, iTriangle, 1\_37T02B0164MAIS, EA, 10, L, 861693034634170, KA01I2000, 1, 26122017, 115947, 28.358885, N, 76.928047, E, 0.0, 137, 13, 241.0, 1.05, 0.74, AirTel, 0, 1, 11.6, 4.0, 1, C, 23, 404, 10, 0209, 6d17, 36, aa1a, 0209, 32, d2fc, 0209, 28, 6d18, 0209, 28, d2fb, 0209, 0000, 000, 003197, 0.0, 0.0, 0, ()*10$ 

## Satisfactory.

Prepared By		Checked By	
SONIA NAIN Assistant Manager	TOTAL SEGMENT ELICHENTS SON	MADHUSUDAN JOSHI Deputy General Manager	Page 15 of 65 + Drwg (03Nos.) [56955]





Date: 31.01.2018

## Annexure - VIII

## 8.0 Vibration Test as per of IS: 9000 (Part8-1981):

#### 8.1 Test Conditions:

ICAT Sample I.D	ICAT/AEEL/56955/04	
DUT Operation During Test	Non-Operating Mode	

## 8.2 Test Method and Test Specifications:

Frequency	10Hz – 55Hz – 10Hz		•	
Displacement	1.5 mm			
Duration	3 Hours (1 Hours on each axis)			

## 8.3 Acceptance Criteria:

During and after the test the VLT with Emergency Button shall be tested for the connectivity to server and its capability to send two location messages.

## 8.4 Test Observations / Result:

#### Observations:

No deformation, crack, looseness or any other harmful defect observed on the DUT(s) after the test. DUT was functionally OK in operation after the test.

### Results:

### **Before Test:**

## **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634170,NM,26122017045008,A,28.359047,N,76.928009,E,239.0,0.0, 0,G,KA01I2000,+917406466262\*4A

### **PVT IP Data:**

\$Header,iTriangle,1\_37T02B0164MAI\$,EA,10,L,861693034634170,KA01I2000,1,26122017,044920,28.35 9045,N,76.928009,E,0.0,182,13,240.0,1.10,0.76,AirTel,1,1,11.6,4,0,1,C,23,404,10,0209,6d17,23,d2fc,020 9,23,aa1a,0209,15,b2f8,0209,13,d2fb,0209,0001,00,002830,0.0,0.0,0()\*5A

## After Test:

## **Emergency IP Data:**

\$Header,iTriangle,EMR,861693034634170,NM,26122017105619,A,28.359192,N,76.928047,E,246.0,0.0, 0,G,KA01I2000,+917406466262\*42

## **PVT IP Data:**

 $$Header, iTriangle, 1\_37T02B0164MAIS, EA, 10, L, 861693034634170, KA01I2000, 1, 26122017, 105612, 28.359167, N, 76.928047, E, 0.0, 56, 12, 246.0, 1.11, 0.84, AirTel, 0, 1, 11.6, 4.0, 1, C, 22, 404, 10, 0209, 6d17, 27, aa1a, 0209, 26, d2fc, 0209, 23, 6d18, 0209, 18, d2fb, 0209, 0000, 00, 003126, 0.0, 0.0, 0, ()*26$ 

#### Satisfactory

Prepared By		Checked By	
Jania Sonja najn	MANESAR A	MADHUSUDAN JOSHI	Page 16 of 65 + Drwg (03Nos.)
Assistant Manager		Deputy General Manager	[56955]